


NOTE The interior of the vent piping is Division 1. Cross hatching has been omitted for drawing clarity.

**Figure 14—Process Equipment Vent in a Nonenclosed Adequately Ventilated Area (See 8.2.3.1)**



**Figure 2—Adequately Ventilated Nonenclosed Area Adjacent to a Classified Area (Section 6.4.1)**